

COVID-19 ► CLEAR THE AIR

Maximize fresh air “in”

Clean with MERV-13 / HEPA filters or units

Increase ventilation to 4 to 6 fresh / clean ACH

Monitor CO2 levels in occupied spaces (1000 ppm max)

Assess and **Post** room ACH and/or CO2 levels

Target: > 6 to 12 ACH

Good: 5-6 ACH

Fair: 4-5 ACH

Minimum: 3-4 ACH

Poor: <3 ACH

